

Approved Organization Certificate

Mr. Gabriel Massey
General Manager
Able Aerospace Services, Inc.

The undermentioned organization is approved pursuant to Article 20, Paragraph 1 of Civil Aeronautics Law.

1. Approved Organization

Able Aerospace Services, Inc.

2. Address

7706 East Velocity Way Mesa, AZ 85212 USA

3. Category

The capability to perform repair or alteration of aircraft components

4. Rating

Rotor, Transmission, Mechanical/Electric Accessories and Major parts

5. Limitation

See the attachment

6. Validity Period

From December 11, 2017 to December 10, 2019

Date Issued : December 6, 2017

Keiichi ISHII

Minister of Land, Infrastructure, Transport and Tourism

Kind of model and classification of work for category

1. Kind of model for aircraft components

Kind of model : Rotor (Inner Parts are specified in the Appendix 4 and 15 of the Approved Organization Exposition)

Nomenclature	Type of component
Main Rotor Hub Assembly	204-012-101-(), 206-010-100-(), 206-011-100-(), 407-010-100-(), 412-010-100-(), 429-110-100-()
Main Rotor Hub and Sleeve Assembly	204-011-401-()
Swashplate Assembly	204-011-400-(), 206-010-450-(), 350A37-1004-(), 406-010-401-(), 412-010-401-(), 412-010-402-(), 429-010-400-()
Tail Rotor Hub Assembly	206-011-749-(), 407-012-101-(), 204-011-801-(), 206-011-810-(), 212-011-701-(), 222-012-701-(), 429-012-101-()


Kind of model : Transmission (Inner Parts are specified in the Appendix 4 and 15 of the Approved Organization Exposition)

Nomenclature	Type of component
Main Transmission Assembly	206-040-002-(), 206-040-004-(), 204-040-009-(), 205-040-001-(), 212-040-001-(), 407-040-006-(), 412-040-002-(), 412-040-004-(), 412-706-029-(), 429-040-006-(), 430-040-003-()
Tail Gearbox Assembly	206-040-400-(), 206-040-402-(), 212-040-004-(), 406-040-400-(), 412-706-029-(), 429-042-001-()
42 Degree Gearbox Assembly	212-040-003-(), 412-040-006-(), 412-706-029-()

Kind of model : Mechanical/Electric Accessories and Major parts (Include inner Parts)

Type of component : As specified in the Appendix 4 and 15 of the Approved Organization Exposition

2. Classification of Work: Repair



事業場認定書

Able Aerospace Services, Inc.
General Manager
Gabriel Massey 殿

航空法第20条第1項の規定により、下記のとおり認定する。

記

事業場の名称	Able Aerospace Services, Inc.
事業場の所在地	7706 East Velocity Way Mesa, AZ 85212 USA
業務の能力	装備品の修理又は改造の能力
業務の範囲	回転翼、トランスミッション、機械補機、電気補機及び主要構成品に係る業務
限定	裏面のとおり
有効期間	平成29年12月11日から平成31年12月10日まで
備考	

発行年月日 平成29年12月6日

国土交通大臣 石井 啓



業務の能力に係る種類、型式及び作業の区分についての限定

1. 装備品の種類及び型式

種類：回転翼に係る業務（内部部品は業務規程 Appendix 4 及び 15 による）

名 称	型 式
Main Rotor Hub Assembly	204-012-101-(), 206-010-100-(), 206-011-100-(), 407-010-100-(), 412-010-100-(), 429-110-100-()
Main Rotor Hub and Sleeve Assembly	204-011-401-()
Swashplate Assembly	204-011-400-(), 206-010-450-(), 350A37-1004-(), 406-010-401-(), 412-010-401-(), 412-010-402-(), 429-010-400-()
Tail Rotor Hub Assembly	206-011-749-(), 407-012-101-(), 204-011-801-(), 206-011-810-(), 212-011-701-(), 222-012-701-(), 429-012-101-()

種類：トランスミッションに係る業務（内部部品は業務規程 Appendix 4 及び 15 による）

名 称	型 式
Main Transmission Assembly	206-040-002-(), 206-040-004-(), 204-040-009-(), 205-040-001-(), 212-040-001-(), 407-040-006-(), 412-040-002-(), 412-040-004-(), 412-706-029-(), 429-040-006-(), 430-040-003-()
Tail Gearbox Assembly	206-040-400-(), 206-040-402-(), 212-040-004-(), 406-040-400-(), 412-706-029-(), 429-042-001-()
42 Degree Gearbox Assembly	212-040-003-(), 412-040-006-(), 412-706-029-()

種類：機械補機、電気補機及び主要構成部品（内部部品を含む）

型式：業務規程 Appendix 4 及び 15 による

2. 作業の区分

修理